Original (to the person ordering the work)

ELECTRICAL INSTALLATION CONDITION REPORT

Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installations

PART 1 : DETAILS OF THE CONTRACTOR, CLIENT AND INSTAL	.ATION								
DETAILS OF THE CONTRACTOR Trading Title: Flex Electrical Services Address: 43 The Crescent, Blidworth, Mansfield	DETAILS OF THE CLIENT Contractor Reference Number (CRN): N/A Name: Trevor Parr Associates Address: 90 Paget Street, LOUGHBOROUGH, Leicestershire	DETAILS OF THE INSTALLATION Occupier: Tenants Address: 28 Granville Street, LOUGHBOROUGH, Leicestershire							
Postcode: NG21 OSE Tel No: 07773888063	Postcode: LE11 5DT Tel No: N/A	Postcode: LE11 3BN Tel No: N/A							
PART 2 : PURPOSE OF THE REPORT									
Purpose for which this report is required: Existing periodic inspection due	to expire								
Date(s) when inspection and testing was carried out: 07/07/2021) Records available: (ailable: (
PART 3: SUMMARY OF THE CONDITION OF THE INSTALLATIO	N								
General condition of the installation (in terms of electrical safety): Wired under the 16th edition BS7671 wiring regulation with brown/blue	e pvc twin/earth cable, all circuits are in good condition, plastic single RC	CD consumer unit some circuits not RCD protected.							
Estimated age of electrical installation: (1.5) years Evidence of	additions or alterations: (allation is: Satisfactory XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX							
PART 4: DECLARATION									
existing installation, hereby CERTIFY that the information in this report, includin stated extent of the installation and the limitations on the inspection and testing. Name (capitals): PETER WILSON REVIEWED BY	Signature: Pullson	essment of the condition of the electrical installation taking into account the Date: 07/07/2021							
Name (capitals):	Signature:	Date:							

^{*}An unsatisfactory assessment indicates that dangerous (CODE C1) and/or potentially dangerous (CODE C2) conditions have been identified in PART 6, or that Further Investigation (CODE FI) without delay is required.

Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installations

PART 5 · N	JEXT I	INSPECTION
I AILL J. I		INDI EVITON

I/We (as indicated on page 1) recommend, subject to the necessary remedial work being taken, this installation should be further inspected and tested after an interval of not more than 5... years/**XXXX*** (delete as appropriate) Give reason for recommendation: Installation is in good enough condition for continued use so allowed maximum time for next inspection for rented accommodation.

PART 6:	: OBSERVATIONS AND RECOMMENDATIONS FOR ACTIONS TO BE TAKEN					
CODES:	One of the following Codes, as appropriate, has been allocated to each of the observations made below to indicate to the person(s) responsible for the electrical installation the degree of urgency for remedial action Risk of injury. Immediate r		E C2 'Potentially Dangerous' ent remedial action required	CODE C3 'Improvement Recommended'	'Furthe	CODE FI Investigation Required'
	to the Schedule of Items Inspected (see PART 10), the attached Schedule of Circuit Details and Test Results (se			PART 7:		
There are	e no items adversely affecting electrical safety (), OR The following observations and recomme	endations for action are mad	e:			
Item No	Observation(5.6 Consumer unit made from combustable material, BS 7671 16th edition single RCD	s))	Code (C3	Location Reference
(2)	5.14Circuits 3/4 no RCD protection wired under the 16th edition BS 7671 regulations				(C3)	()
()	()	()	()
())	()	()
()	()	()	()
()	()	()	()
()	()	()	()
()	()	()	()
()	()	()	()
()	()	()	()
()	()	()	()
()	(••••)	()	()
()	(•••••)	()	()
()	(•••••)	()	()
()	(•••••)	()	()
()	()	()	()
()	()	()	()
()	()	()	()
Additiona	al pages? (None State page numbers: (N/A)					
Immediat	te action required for items: (N/A) Improvement reco	mmended for items: (.1.	2)
Urgent re	emedial action required for items: (N/A) Further investigati		/A		

^{*}The proposed date for the next inspection should take into consideration any legislative or licensing requirements and the frequency and quality of maintenance that the installation can reasonably be expected to receive during its intended life. The period should be agreed between relevant parties.

Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installations

PART 7 : DETAILS AND LIMITATIONS OF	THE INSPECTION AND TES	TING							
The inspection and testing has been carried out in accordance with BS 7671: 2018, as amended. Cables concealed within trunking and conduits, or cables and conduits concealed under floors, in inaccessible roof space the building or underground, have not been visually inspected unless specifically agreed between the Client and the Inspector prior to inspection. Details of the installation covered by this report. Inspection and testing of distribution board and all final circuits, visual inspection of distributors equipment only, insulation resistance test carried out between live/neutral to earth, live to earth and neutral to earth using blanket test. Agreed limitations including the reasons, if any, on the inspection and testing: No taking up carpets or floor boards, of dismantling fitted units or appliances.									oage No. N/A
Agreed with (print name): MR DOMINIC PARR								R see additional	page No. N/A)
PART 8: SUPPLY CHARACTERISTICS A	AND EARTHING ARRANGE	MENTS							
System type and earthing arrangements TN-C-S: (N/A) TN-S: (/) Other (state): N/A Supply protective device (BS (EN) 1361) Type: (TT: (N/A)	AC 1-phase, 2-wire: (ture of supply parameters minal line voltage, $U^{(1)}$: (N/A) minal line voltage to Earth, $U_0^{(1)}$: (230) minal frequency, $f^{(1)}$: (50) spective fault current, $I_{pf}^{(1)*}$: (1.2) ernal loop impedance, $Z_e^{(1)*}$: (0.21)		
PART 9 : PARTICULARS OF INSTALLAT	ION REFERRED TO IN THIS	REPORT							
Means of Earthing Distributor's facility: (Main protective conductors Earthing conductor: (material Copper csa Connection / continuity verified: Main protective bonding conduct (material Copper csa Connection / continuity verified:	()	Main protective bonding connection Water installation pipes: Gas installation pipes: Structural steel: Oil installation pipes: Lightning protection: Other (state): N/A	(Type: Location: No. of poles: Current rating: Where an RCD RCD rated resid	Switch-fuse / Circuit-breaker / F (BS (EN) $60947-3$ (Downstairs front bedroor $\binom{2}{100}$) A is used as the main switch dual operating current, $I_{\Delta n}$: operating time: $\binom{N/A}{100}$ ms)	ng of device: g:	(N/A) MA (N/A) mA (N/A) ms

All fields must be completed. Enter either, as appropriate: '✓' if Acceptable condition;

'N/A' if Not applicable;

'LIM' if a Limitation exists;

or Code appropriately - CODE 'C1', 'C2', 'C3' or 'FI' (codes to be recorded in PART 6, with additional comments (where appropriate) on attached numbered sheets)

^{*}Where the installation is supplied by more than one source, the higher or highest values of prospective fault current, Ipf, and external earth fault loop impedance, Ze, must be recorded.

Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installations

PART 10 : SCHEDULE OF ITEMS INSPECTED		
External condition of electrical intake equipment (visual inspection on (If inadequacies are identified with the intake equipment, it is recommend the person ordering the report informs the appropriate authority.)		5.24 Single-pole switching or protective devices in line conductors only: () 5.25 Protection against mechanical damage where cables
1.1 Service cable: (b.1 Adequacy of working space / accessibility of equipment: (
2. Presence of adequate arrangements for parallel or switched alternative sources 2.1 Adequate arrangements where a generating set operates as a switched alternative to the public supply: 2.2 Adequate arrangements where generating set operates in parallel with the public supply: 2.3 Presence of alternative / additional supply arrangement warning notice(s) at or near equipment, where required: (N/A)	5.7 Enclosure not damaged / deteriorated so as to impair safety: 5.8 Presence and effectiveness of obstacles: 5.9 Presence of main switch(es), linked where required:	6.1 Identification of conductors: 6.2 Cables correctly supported throughout their length: 6.3 Condition of insulation of live parts: 6.4 Non-sheathed cables protected by enclosures in conduit, ducting or trunking: 6.5 Suitability of containment systems for continued use
3. Automatic disconnection of supply 3.1 Main earthing and bonding arrangements a) Presence and condition of distributor's earthing arrangement: (5.13 RCD(s) provided for fault protection – includes RCBOs: (C3) 5.14 RCD(s) provided for additional protection – includes RCBOs: (C3) 5.15 RCD(s) provided for protection against fire – includes RCBOs: (N/A) 5.16 Manual operation of circuit-breakers and RCDs to prove disconnection: (5.17 Confirmation that integral test button/switch causes RCD(s) to trip when operated (functional check)	(indicate extent of sampling in PART 7 of report): (indicate extent of sampling in PART 7 of report): (indication of SPD(s) continued functionality confirmed: (indication of SPD(s) continued functionality confirmed: (indicate extent of sampling in PART 7 of report): (indic
 g) Adequacy of main protective bonding conductor connections: (5.18 Presence of RCD six-monthly retest notice at or near equipment, where required: 5.19 Presence of diagrams, charts or schedules at or near equipment, where required: (to the type and nature of installation: 6.12 Adequacy of protective devices; type and rated current for fault protection: 6.13 Presence and adequacy of circuit protective conductors: 6.14 Co-ordination between conductors and overload protective devices:
3.2 FELV a) Source providing at least simple separation: (N/A b) Plugs, socket-outlets and the like not interchangeable with those of other systems within the premises: (N/A	5.21 Presence of next inspection recommendation label: 5.22 All other required labelling provided: 5.23 Compatibility of protective device(s), base(s) and	and nature of installation and external influences: (

All fields must be completed. Enter either, as appropriate: '✓' if Acceptable condition; 'N/A' if Not applicable;

'LIM' if a Limitation exists;

or Code appropriately - CODE 'C1', 'C2', 'C3' or 'FI' (codes to be recorded in PART 6, with additional comments (where appropriate) on attached numbered sheets)

		Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installa	tions
PART 10 : SCHEDULE OF ITEMS INSPECTED			
Provision of additional protection by an RCD not exceeding 30 mA For all socket-outlets with a rated current not exceeding 32 A, unless exempt: Supplies for mobile equipment with a rated current not exceeding 32 A for use outdoors:	() ()	6.26 Single-pole switching or protective devices in line conductors only: 6.27 Adequacy of connections, including cpcs, within accessories and to fixed and stationary equipment: 7. Isolation and switching 8. Current-using equipment (permanently connected) 8.1 Condition of equipment in terms of IP rating: 8.2 Equipment does not constitute a fire hazard: 8.3 Enclosure not damaged / deteriorated so as to impair safety: 8.4 Suitability for the environment and external influences:)
c) For cables concealed in walls / partitions at a depth of less than 50 mm: d) For cables concealed in walls / partitions containing metal parts regardless of depth: e) Circuits supplying luminaires within domestic (household) premises: Note: Older installations designed prior to BS 7671: 2018 may not have provided with RCDs for additional protection. 6.19 Provision of fire barriers, sealing arrangements and protection against thermal effects: 6.20 Band II cables segregated / separated from Band I cables: 6.21 Cables segregated / separated from non-electrical services: 6.22 Termination of cables at enclosures (indicate extent of sampling in PART 7 of report)	(.)	7.1 Isolators a) Presence and condition of appropriate devices: b) Acceptable location (local / remote): c) Capable of being secured in the OFF position: d) Correct operation verified: e) Clearly identified by position and / or durable markings: f) Warning label posted in situations where live parts cannot be isolated by the operation of a single device: 7.2 Switching off for mechanical maintenance a) Presence and condition of appropriate devices: b) Acceptable location: c) Capable of being secured in the OFF position: () 8.5 Security of fixing: () 8.6 Cable entry holes in ceiling above luminaires, sized or sealed so as to restrict the spread of fire: () List number and location of luminaires inspected on a separate page: a) Correct type of lamps fitted: b) Installed to minimise build-up of heat: c) No signs of overheating to surrounding building fabric: d) No signs of overheating to conductors / terminations: (N/A) N/A N/A Switching off for mechanical maintenance a) Presence and condition of appropriate devices: b) Acceptable location: c) Capable of being secured in the OFF position: (N/A) N/A	() ()))
a) Connections under no undue strain: b) No basic insulation of a conductor visible outside an enclosure: c) Connections of live conductors adequately enclosed: d) Adequacy of connection at point of entry to enclosure: 6.23 Temperature rating of cable insulation addequate: 6.24 Condition of accessories including socket-outlets, switches and joint boxes satisfactory: 6.25 Suitability of accessories for external influences:		d) Correct operation verified: e) Clearly identified by position and / or durable marking(s): 7.3 Emergency switching off / stopping a) Presence and condition of appropriate devices: b) Readily accessible for operation where danger might occur: c) Correct operation verified: 7.4 Functional switching a) Presence and condition of appropriate devices: b) Correct operation (functionality) verified: (N/A) ()
PART 11 : SCHEDULES AND ADDITIONAL PAGES			
Schedule of Inspections Page No(s): (4 & 5		Test Results Additional pages, including data sheets for additional sources None Page No(s): (None Page No(s): (7 Page No(s): (None Pa)

All fields must be completed. Enter either, as appropriate: '√' if Acceptable condition; 'N/A' if Not applicable;

'LIM' if a Limitation exists;

or Code appropriately — CODE 'C1', 'C2', 'C3' or 'FI' (codes to be recorded in PART 6, with additional comments (where appropriate) on attached numbered sheets)

Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installations

PART 12 : SCHEDULE OF CIRCUIT DETAILS AND TEST RESULTS								Circuits/equipment vulnerable to damage when testing 1,2,3,4,7,8,11																		
C	DES for Type of wiring (A) Thermoplastic insulate sheathed cables	ed / (B)	Thermoplas metallic cor	tic cables i nduit	n (C) T	hermoplastio	cables in conduit	(D) Thermoplastic cables in metallic trunking (E) Thermoplastic cables in non-metallic trunking (F) Thermoplastic / SWA cables (G) Thermoplastic						(G) Thermos	mosetting / SWA cables (H) Mineral-insulated cables				(O) other	(0) other - state: N/A						
_	Circuit description		pou	erved		cuit ctor csa	tion)	F	Protective	device		RCD	permitted nstalled e device*		Circu	it impedanc	es (Ω)	·	Insu	ulation resi	stance	>	earth nce, <i>Zs</i>	RCD operating	Test buttons	
Circuit number		Reference Method (BS 7671) Number of points served and served (BS 7671) Number of points served (BS 7671) Time (BS 7671) Time (BS 7671)		Max. disconnecti time (<i>BS 7671</i>)	BS (EN)	Туре	Rating	Short-circuit capacity	Operating current, $I_{\Delta n}$	Maximum per Z_S for instantants protective de	Ring (mea	final circuit ssured end t		(comple	ircuits ete at least column)	Live / Live	Live / Earth	Test voltage DC	Polarity	Max. measured earth fault loop impedance, <i>Zs</i>	time	RCD	AFDE			
					(mm ²)	(mm ²)	(s)			(A)	(kA)	(mA)	(Ω)	r ₁	r _n	r ₂	$(R_1 + R_2)$	R ₂	(MΩ)	(MΩ)	(V)	(1)	(Ω)	(ms)	(1)	(1)
İ	Upstairs lights	Α	В	9	1		0.4	61009	В	6	6	30	7.28	N/A	N/A	N/A	1.47	N/A	>500	>500	500	1	1.69	19.3	~	N/A
2	Downstairs lights	Α	В	7	1		0.4	61009	В	6	6	30	7.28	N/A	N/A	N/A	1.05	N/A	>500	>500	500	~	1.27	19.3	~	N/A
}	Smoke Alarms	Α	В	4	1		0.4	60898	В	6	6	N/A	7.28	N/A	N/A	N/A	0.98	N/A	>500	>500	500	~	1.20	N/A	N/A	N/A
1	Cellar lights	Α	С	2	1	1	0.4	60898	В	6	6	N/A	7.28	N/A	N/A	N/A	0.60	N/A	>500	>500	500	~	0.82	N/A	N/A	N/A
5	Spare																									
3	Spare																									
7	Ground floor Shower	Α	В	1	10	4	5	60898	В	40	6	30	1.09	N/A	N/A		0.18	N/A	>500	>500	500	1	0.40	12.5	~	N/A
3	Cooker/Hob	Α	В	2	6		0.4	60898	В	32	6	30	1.37	N/A	N/A		0.19	N/A	>500	>500	500	-	0.41	12.5	'	N/A
)	Upstairs sockets	Α	В	8	2.5		0.4	60898	В	32	6	30	1.37	0.55	0.56		0.36	N/A	>500	>500	500	-	0.58	12.5	~	N/A
10	Downstairs sockets/security alarm	Α	В	15	2.5	1.5	0.4	60898	В	32	6	30	1.37	0.60	0.63	1.00	0.40	N/A	>500	>500	500	1	0.62	12.5	V	N/A
11	1st floor Shower	Α	В	1	10	4	5	60898	В	50	6	30	0.87	N/A	N/A	N/A	0.09	N/A	>500	>500	500	1	0.31	12.5	'	N/A
12	Spare																									
	STRIBUTION BOARD (DB) DETA be completed in every case)	ILS	DB des	ignatio n of DF	n: DB C 3. Down	ne nstairs i	front be	edroom	TEST	ED BY	Na Sid	me (capi	tals): PE	TER WI	LSON	• • • • • • • • • • • • • • • • • • • •		•••••	•••••		_{n:} Duty h 07/07/20		r 	• • • • • • • • • • • • • • • • • • • •	• • • • • • • • • • • • • • • • • • • •	
	BE COMPLETED ONLY IF THE							•	UDICI	NI OE							TEST	INSTR	UMENT				agains	t each in	strumer	ıt used)
	pply to DB is from: (N/A														s: (N/A	.)	l	unction:					nuity:			
	ercurrent protection device for the di sociated RCD (if any) Type: (BS EN					S EN lo. of po				-) A) m <i>A</i>		0	oting ti	ıe (N/A	\ ma	Insulat N/A	ion resis			i	Earth N/A	fault lo	oop impe	dance:	
	aracteristics at this DB Confirmation								_				•	_			Farth e	lectrode	e resistan	ce.	· i	RCD: N/A				
	onart is based on the model forms shown in Ar							iaure is not t				,	N/A					,								

GENERAL CONTINUATION SHEET

23650665

NOTES	
st/2nd floor	Section 701 Installation containing a bath or shower

NOTES FOR RECIPIENT

THIS CONDITION REPORT IS AN IMPORTANT AND VALUABLE DOCUMENT WHICH SHOULD BE RETAINED FOR FUTURE USE

The purpose of periodic inspection is to determine, so far as is reasonably practicable, whether an electrical installation is in a satisfactory condition for continued service. This report provides an assessment of the condition of the electrical installation identified overleaf at the time it was inspected and tested, taking into account the stated extent of the installation and the limitations of the inspection and testing.

This report has been issued in accordance with the national standard for the safety of electrical installations, BS 7671: 2018 – Requirements for Electrical Installations.

The report identifies any damage, deterioration, defects and/or conditions found by the inspector which may give rise to danger (see PART 6), together with any items for which improvement is recommended.

If you were the person ordering this report, but not the user of the installation, you should pass this report, or a full copy of it including these notes, the schedules and additional pages (if any), immediately to the user.

This report should be retained in a safe place and shown to any person inspecting or undertaking further work on the electrical installation in the future. If you later vacate the property, this report will provide the new user with an assessment of the condition of the electrical installation at the time the periodic inspection was carried out.

Where the installation incorporates a residual current device (RCD) there should be a notice at or near the device stating that it should be tested every six months. For safety reasons it is important that this instruction is followed.

For safety reasons, the electrical installation should be re-inspected at appropriate intervals by a skilled person or persons, competent in such work.

The recommended date by which the next inspection should be carried out is stated in PART 5 of this report. There should also be a notice at or near the main switchboard or distribution board/consumer unit indicating when the next inspection of the installation is due.

You should have received the report marked 'Original' and the contractor should have retained the report marked 'Duplicate'.

This report form is intended to be issued only for the purpose of reporting on the condition of an existing electrical installation and must not be issued to certify new electrical installation work including the replacement of a distribution board or consumer unit.

The report consists of at least six numbered pages. Additional numbered pages may have been provided to permit further relevant information relating to the installation to be recorded. For installations having more than one distribution board or more circuits than can be recorded on PART 12, one or more additional *Schedules of Circuit Details and Test Results* should form part of the report. The report is invalid if any of the schedules identified in PART 10 are missing.

PART 7 (Details and limitations) should identify fully the extent of the installation covered by this report and any limitations on the inspection and testing. The inspector should have agreed these aspects with the person ordering the report and with other interested parties (licensing authority, insurance company, mortgage provider and the like) before the inspection was carried out.

Operational limitations may have been encountered during the inspection such as inability to gain access to parts of the installation or to an item of equipment. The inspector should have noted any such limitations in PART 7. It should be noted that the greater the limitations applying to a report, the less its value from the safety aspect.

A declaration should have been given by the inspector in PART 4 of the report. The declaration must reflect the statement given in PART 3, which summarises the observations and recommendations made in PART 6. Where one or more observations have been made in PART 6, the Classification code given to each by the inspector indicates the degree of urgency with which remedial action needs to be taken to restore the installation to a safe working condition.

Where the inspector has indicated an observation as code C1 (danger present) the safety of those using the installation is at risk. Wherever practicable, items classified as (C1) should be made safe on discovery, and it is recommended that a skilled person(s) competent in electrical installation work undertakes the necessary remedial work immediately.

Where the inspector has indicated an observation as code C2 (potentially dangerous) the safety of those using the installation may be at risk, and it is recommended that a skilled person(s) competent in electrical installation work undertakes the necessary remedial work as a matter of urgency.

Where the inspector has indicated that an item requires further investigation (FI), the investigation should be carried out without delay to determine whether danger or potential danger exists. For further guidance on the Classification codes, please see the reverse of page 2.

Where the installation can be supplied by more than one source, such as the public supply and a standby generator or microgenerator, this should be identified in PART 8 Supply Characteristics and Earthing Arrangements, and the Schedules of Circuit Details and Test Results (PART 12) compiled accordingly.

Where inadequacies in the intake equipment have been observed (Item 1 of PART 10), the person ordering the inspection should inform the distributor and/or supplier as appropriate.

Should the person ordering this report have reason to believe that it does not reasonably reflect the condition of the electrical installation reported on, that person should in the first instance raise the specific concerns in writing with the contractor.

GUIDANCE FOR RECIPIENTS ON THE CLASSIFICATION CODES

Only one Classification code should be given for each recorded Observation

Classification code C1 (Danger present)

Where an observation has been given a Classification code C1, the safety of those using the installation is at risk and immediate remedial action is required.

The person responsible for the maintenance of the installation is advised to take action without delay to remedy the observed deficiency in the installation, or to take other appropriate action (such as switching off and isolating the affected part(s) of the installation) to remove the danger. The contractor issuing this report will be able to provide further advice.

NICEIC makes available 'Electrical Danger Notification' forms to enable inspectors to record, and then to communicate to the person ordering the report, any dangerous condition discovered.

Classification code C2 (Potentially dangerous)

Classification code C2 indicates that, whilst those using the installation may not be at immediate risk, urgent remedial action is required to remove potential danger. The contractor issuing this report will be able to provide further advice.

It is important to note that the recommendation given at PART 5 of this report (Next Inspection) for the maximum interval until the next inspection is conditional upon all items which have been given a Classification code C1 and code C2 being remedied immediately and as a matter of urgency, respectively.

It would not be reasonable for the inspector to indicate that the installation is in a satisfactory condition if any observation in this report has been given a code C1 or code C2 classification.

Classification code C3 (Improvement recommended)

Where an observation has been given a Classification code C3, the inspection and/or testing has revealed a non-compliance with the current safety standard which, whilst not presenting immediate or potential danger, would result in a significant safety improvement if remedied. Careful consideration should be given to the safety benefits of improving these aspects of the installation. The contractor issuing this report will be able to provide further advice.

Code FI (Further investigation required without delay)

It should usually be possible for the inspector to attribute a Classification code to each observation without indicating a need for further investigation.

However, where 'FI' has been entered against an observation the inspector considers that further investigation of that observation is likely to reveal danger or potential danger that, due to the agreed extent or limitations of the inspection and/or testing, could not be fully identified at the time.

It would not be appropriate for the inspector to indicate that the installation is in a satisfactory condition if there is reasonable doubt as to whether danger or potential danger exists. Consequently, where the inspector has indicated 'Further investigation required without delay' (FI) the overall assessment of the installation (PART 3) should be marked as 'Unsatisfactory'.

If the inspector has indicated that an observation requires further investigation without delay, the person ordering this report is advised to arrange for the contractor issuing the report (or another skilled person or persons competent in such work) to undertake further examination of that aspect of the installation as a matter of urgency, to determine whether or not danger or potential danger exists.

Further information

Further information on the application of Classification codes, primarily aimed at inspectors but of possible interest to persons ordering condition reports, can be found in Electrical Safety First's Best Practice Guide No 4 Electrical installation condition reporting: Classification Codes for domestic and similar electrical installations. The guide can be viewed or downloaded free of charge from www. electricalsafetyfirst.org.uk