IPM18C

ELECTRICAL INSTALLATION CONDITION REPORT

Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installations

PART 1 : DETAILS OF THE CONTRACTOR, CLIENT AND INSTALL	ATION	
DETAILS OF THE CONTRACTOR Trading Title: Flex Electrical Services Address: 43 The Crescent, Blidworth, Mansfield	DETAILS OF THE CLIENT Contractor Reference Number (CRN): N/A Name: Trevor Parr Associates Address: 90 Paget Street, LOUGHBOROUGH, Leicestershire	DETAILS OF THE INSTALLATION Occupier: Tenants Address: 24 Granville Street, LOUGHBOROUGH, Leicestershire
Postcode: NG21 0SE Tel No: 07773888063	Postcode: LE11 5DT Tel No: N/A	Postcode: LE11 3BN Tel No: N/A
PART 2 : PURPOSE OF THE REPORT		
Purpose for which this report is required: Existing periodic inspection due to	o expire	
Date(s) when inspection and testing was carried out: (07/07/2021) Records available: () Previous inspection report av	railable: (
PART 3 : SUMMARY OF THE CONDITION OF THE INSTALLATION	N	
	of red/black and brown/blue pvc twin/earth cable, single RCD consumer cuits 1,2,3,8.9. Circuits wired in brown/blue pvc twin/earth in good condit	
Estimated age of electrical installation: (³⁰) years Evidence of	additions or alterations: (allation is: Satisfactory XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
PART 4 : DECLARATION		
	nstallation, particulars of which are described in PART 7, having exercised reaso g the observations (page 2) and the attached schedules, provides an accurate ass Signature:	essment of the condition of the electrical installation taking into account the
*An unsatisfactory assessment indicates that dangerous (CODE C1) and/or potentially dang	gerous (CODE C2) conditions have been identified in PART 6, or that Further Investigation (Co	ODE FI) without delay is required.

7

IPM18C

ELECTRICAL INSTALLATION CONDITION REPORT

Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installations

PART 5: NEXT INSPECTION	
I/We (as indicated on page 1) recommend, subject to the necessary remedial work being taken, this installation should be further inspected and tested after an interval of not more than 5.	years/XXXXXS* (delete as appropriate)
PART 6 : OBSERVATIONS AND RECOMMENDATIONS FOR ACTIONS TO BE TAKEN	
CODES: One of the following Codes, as appropriate, has been allocated to each of the observations made below to indicate to the person(s) responsible for the electrical installation the degree of urgency for remedial action CODE C1 'Danger Present' CODE C2 'Potentially Dangerous' CODE C3 'Improvement Recommended'	CODE FI 'Further Investigation Required'
Referring to the Schedule of Items Inspected (see PART 10), the attached Schedule of Circuit Details and Test Results (see PART 12), and subject to any agreed limitations listed in PART 7: There are no items adversely affecting electrical safety (), OR The following observations and recommendations for action are made: Observations (1) (3.1 h)Main protective bonding to incoming water supply not visible only can verify by feel and testing	Code Location Reference (C3) (
() () () ()	() () () ()
() () Additional pages? (None) State page numbers: (N/A) Immediate action required for items: (N/A) Improvement recommended for items: (1,2,3,4,5,6,7,8,9	() ()
Immediate action required for items: (N/A Urgent remedial action required for items: (N/A Improvement recommended for items: (N/A Further investigation required for items: (N/A)

*The proposed date for the next inspection should take into consideration any legislative or licensing requirements and the frequency and quality of maintenance that the installation can reasonably be expected to receive during its intended life. The period should be agreed between relevant parties.

IPM18C

ELECTRICAL INSTALLATION CONDITION REPORT

Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installations

PART 7 : DETAILS AND LIMITATIONS O	F THE INSPECTION AND TE	STING							
The inspection and testing has been carried out in the building or underground, have not been visual Details of the installation covered by this repor test carried out between live/neutral to ear Agreed limitations including the reasons, if any	ince (sei	e additional pac	ae No. N/A						
	OMINIC PARR (se	ARR . (see additional page No. <mark>N/A</mark>) . (see additional page No. <mark>N/A</mark>)							
PART 8 : SUPPLY CHARACTERISTICS	AND EARTHING ARRANG	EMENTS							
System type and earthing arrangements TN-C-S: (TT: (<u>N/A</u>)	AC DC Confirmation o	pe of live conductors 1-phase, 2-wire: (♥) 3-phase, 3-wire: (N/A) 2-wire: (N/A) 3-wire: (N/A) f supply polarity: of supply (<i>as detailed on attached so</i>	3-phase, 4 .) Other: (-wire: (<u>N/A</u>) -wire: (<u>N/A</u>) //A) (¥)	Nature of supply parameters Nominal line voltage, <i>U</i> ⁽¹⁾ : Nominal line voltage to Earth, <i>U</i> Nominal frequency, <i>f</i> ⁽¹⁾ : Prospective fault current, <i>I_{pf}</i> ⁽¹⁾ External loop impedance, <i>Z_e</i> ⁽¹⁾	U ₀ ⁽¹⁾ : (230 (50) (1)*: (1.1	0) V	By enquiry, measurement, or by calculation
PART 9 : PARTICULARS OF INSTALLA	TION REFERRED TO IN THI	S REPORT							
Means of Earthing Distributor's facility: (Main protective conductors Earthing conductor: (material Copper Connection / continuity verified Main protective bonding conduct (material Copper Connection / continuity verified	() ctors: sa ¹⁰ mm ²)	Main protective bonding connect Water installation pipes: Gas installation pipes: Structural steel: Oil installation pipes: Lightning protection: Other (state): N/A	() () (N/A) (N/A) (N/A)	Type: Location: No. of poles: Current rating: Where an RCD is RCD rated residu	witch-fuse / Circuit-breaker / $(BS (EN) .60947-3)$ (Downstairs front bedroo) (2) (100) A s used as the main switch val operating current, $I_{\Delta n}$: perating time: (N/A) ms)		(N/A) A (230) V (N/A) mA (N/A) ms

*Where the installation is supplied by more than one source, the higher or highest values of prospective fault current, I of, and external earth fault loop impedance, Z_e, must be recorded.

All fields must be completed. Enter either, as appropriate: '\screwtail' if Acceptable condition; 'N/A' if Not applicable;

'LIM' if a Limitation exists; or Code

or Code appropriately – CODE 'C1', 'C2', 'C3' or 'FI' (codes to be recorded in PART 6, with additional comments (where appropriate) on attached numbered sheets)

This report is based on the model forms shown in Appendix 6 of *BS 7671* Published by Certsure LLP @ Copyright Certsure LLP (July 2018) Warwick House, Houghton Hall Park, Houghton Regis, Dunstable, LU5 5ZX

ELECTRICAL INSTALLATION CONDITION REPORT

Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installations

Original (to the person ordering the work)

PART 10 : SCHEDULE OF ITEMS INSPECTED

	ernal condition of electrical intake equipment (visual inspect		4. Other methods of protection	(<u>N/A</u>)	5.24 Single-pole switching or protective devices in line conductors only: ()
	adequacies are identified with the intake equipment, it is recon person ordering the report informs the appropriate authority.)	nmended	Details should be provided on separate sheets: Page N	o. (<mark>N/A</mark>)	5.25 Protection against mechanical damage where cables
			5. Distribution equipment		enter equipment: ()
-	ervice cable: () 1.2 Service head:	()	5.1 Adequacy of working space / accessibility of equipment:	()	5.26 Protection against electromagnetic effects where cables enter ferrromagnetic enclosures: (N/A
	arthing arrangement: () 1.4 Meter tails:	() N/A	5.2 Security of fixing:	()	·
	Aetering equipment: () 1.6 Isolator (where present):	()	5.3 Condition of insulation of live parts:	(•	6. Distribution / final circuits
	sence of adequate arrangements for parallel or switched rnative sources		5.4 Adequacy / security of barriers:	(N/A ()	6.1 Identification of conductors:
	dequate arrangements where a generating set operates as a		5.5 Condition of enclosure(s) in terms of IP rating:	()	6.2 Cables correctly supported throughout their length: (LIM
	witched alternative to the public supply:	(N/A	5.6 Condition of enclosure(s) in terms of fire rating:	(C3)	6.3 Condition of insulation of live parts: ()
	dequate arrangements where generating set operates in	₍ Ν/Α)	5.7 Enclosure not damaged / deteriorated so as to impair safety:	()	6.4 Non-sheathed cables protected by enclosures in conduit, ducting or trunking: ()
	arallel with the public supply:	()	5.8 Presence and effectiveness of obstacles:	(N/A	
	resence of alternative / additional supply arrangement varning notice(s) at or near equipment, where required:	(N/A	5.9 Presence of main switch(es), linked where required:	()	6.5 Suitability of containment systems for continued use (including flexible conduit): (N/A)
		()	5.10 Operation of main switch(es) (functional check):	(•	6.6 Cables correctly terminated in enclosures
	matic disconnection of supply Iain earthing and bonding arrangements		5.11 Correct identification of circuit protective devices:	()	(indicate extent of sampling in PART 7 of report):
a		. (5.12 Adequacy of protective devices for prospective fault current:	()	6.7 Indication of SPD(s) continued functionality confirmed:
b	5 5		5.13 RCD(s) provided for fault protection – includes RCBOs:	(N/A ()	6.8 Adequacy of AFDD(s), where specified: (N/A)
	if present:	(N/A ()	5.14 RCD(s) provided for additional protection – includes RCBOs:	(C3	6.9 Confirmation that conductor connections, including
С) Adequacy of earthing conductor size:	()	5.15 RCD(s) provided for protection against fire – includes RCBOs:	(N/A)	connections to busbars are correctly located in terminals and are tight and secure:
d) Adequacy of earthing conductor connections:	()	5.16 Manual operation of circuit-breakers and RCDs to		
e) Accessibility of earthing conductor connections:	()	prove disconnection:	()	6.10 Examination of cables for signs of unacceptable thermal and mechanical damage / deterioration:
f)	Adequacy of main protective bonding conductor size(s):	()	5.17 Confirmation that integral test button/switch causes RCD(s) to trip when operated (functional check)	(6.11 Adequacy of cables for current-carrying capacity with regard
g) Adequacy of main protective bonding conductor connections		5.18 Presence of RCD six-monthly retest notice at or near	()	to the type and nature of installation:
h) Accessibility of main protective bonding connections:	(C3	equipment, where required:	(6.12 Adequacy of protective devices; type and rated current for
i)	Accessibility and condition of other protective		5.19 Presence of diagrams, charts or schedules at or near equipmen	t,	fault protection: ()
	bonding connections:	()	where required:	()	6.13 Presence and adequacy of circuit protective conductors: ()
j)	Provision of earthing / bonding labels at all appropriate locations:	(5.20 Presence of non-standard (mixed) cable colour warning		6.14 Co-ordination between conductors and overload
		()	notices at or near equipment, where required:	()	
3.2 F		,N/Α 、	5.21 Presence of next inspection recommendation label:	()	6.15 Cable installation methods / practices appropriate to the type and nature of installation and external influences:
a	,	(*)	5.22 All other required labelling provided:	()	6.16 Cables where exposed to direct sunlight of a suitable type or
b	 Plugs, socket-outlets and the like not interchangeable with those of other systems within the premises: 	(N/A ()	5.23 Compatibility of protective device(s), base(s) and other components:	(adequately protected against solar radiation: (C3
		()	ouror componente.	()	6.17 Cables adequately protected against damage and abrasion: (LIM)

All fields must be completed. Enter either, as appropriate: '\scriptistic if Acceptable condition; 'N/A' if Not applicable;

'LIM' if a Limitation exists;

or Code appropriately – CODE 'C1', 'C2', 'C3' or 'FI' (codes to be recorded in PART 6, with additional comments (where appropriate) on attached numbered sheets)

IPM18C

ELECTRICAL INSTALLATION CONDITION REPORT

Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installations

PART 10 : SCHEDULE OF ITEMS INSPECTED		
 6.18 Provision of additional protection by an RCD not exceeding 30 mA a) For all socket-outlets with a rated current not exceeding 32 A, unless exempt: b) Supplies for mobile equipment with a rated current not exceeding 32 A for use outdoors: c) For cables concealed in walls / partitions at a depth of less than 50 mm: d) For cables concealed in walls / partitions containing metal parts regardless of depth: e) Circuits supplying luminaires within domestic (household) premises: Mote: Older installations designed prior to BS 7671: 2018 may not have been provided with RCDs for additional protection. 6.19 Provision of fire barriers, sealing arrangements and protection against thermal effects: 6.20 Band II cables segregated / separated from Band I cables: (LIM) 6.21 Cables segregated / separated from Band I cables: () b) No basic insulation of a conductor visible outside an enclosure: () c) Connections of ive conductors adequately enclosed: () c) Connections of cable insulation addequate: () c) Connections including socket-outlets, switches and joint boxes satisfactory: c) Calles supplice accessories for external influences: 	 6.26 Single-pole switching or protective devices in line conductors only: 6.27 Adequacy of connections, including cpcs, within accessories and to fixed and stationary equipment: 7.1 Isolation and switching 7.1 Isolators a) Presence and condition of appropriate devices: b) Acceptable location (local / remote): c) Capable of being secured in the OFF position: d) Correct operation verified: e) Clearly identified by position and / or durable markings: f) Warning label posted in situations where live parts cannot be isolated by the operation of a single device: N/A) c) Capable of being secured in the OFF position: d) Correct operation of a ppropriate devices: minut and the operation of a single device: minut and the operation of a single device: minut and the operation of a ppropriate devices: minut and the operation of a single device: minut and the operation of a ppropriate devices: minut and the operation of a poperiate devices: minut and the operation of a poperiate devices: minut and the operation of a propriate devices: minut and the operation operation operation where danger might occur: minut and the operation operation where danger might occur: minut and the operation of appropriate devices: minut and the operation of appropriate devices: minut and the operation of appropriate devices: minut and the operation where danger might occur: minut and the operation of appropriate devices: minut and the operation of appropriate devices: minut and the operation of appropriate devices: minut and the operation operation where danger might occur: minut and the opera	8. Current-using equipment (permanently connected) 8.1 8.1 Condition of equipment in terms of IP rating: 8.2 Equipment does not constitute a fire hazard: (
PART 11 : SCHEDULES AND ADDITIONAL PAGES		
Schedule of Inspections Schedule of Circuit Details an	d Test Results Additional pages, including data sheets Special install	ations or locations Continuation sheets
Page No(s): (4 & 5	for additional sources (indicated in it) Page No(s): (None Page No(s): Page No(s):	tem 9. above) (7) Page No(s): (None)
	The pages identified are an essential part of this report (see Regulation 653.2,	/.

All fields must be completed. Enter either, as appropriate: '\screwt' if Acceptable condition; 'N/A' if Not applicable;

t applicable; **'LIM**' if a Limitation exists; o

or Code appropriately – CODE 'C1', 'C2', 'C3' or 'FI' (codes to be recorded in PART 6, with additional comments (where appropriate) on attached numbered sheets)

This report is based on the model forms shown in Appendix 6 of *BS 7671* Enter a (✓) or value in the respective fields, as appropriate. Published by Certsure LLP @ Copyright Certsure LLP (July 2018) Warwick House, Houghton Hall Park, Houghton Regis, Dunstable, LU5 5ZX

IPM18C

ELECTRICAL INSTALLATION CONDITION REPORT

Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installations

PART 12 : SCHEDULE OF CIRCUIT DETAILS AND TEST RESULTS						Circuits/equipment vulnerable to damage when testing 1,3,3a,4,5,7,10,11																				
CODES for Type of wiring (A) Thermoplastic insulated / (B) Thermoplastic cables in (C) Thermoplastic cables in non-metallic conduit						(D) Thermop	(D) Thermoplastic cables in mon-metallic trunking (E) Thermoplastic cables in non-metallic trunking (F) Thermoplastic / SWA cables (G) Thermoplastic					osetting / SWA cables (H) Mineral-insulated cables (O) other - state: N/A														
her	Circuit description			of points served	Cir	cuit ctor csa	ю		Protective		1	RCD			dances (Ω)		Insu	ulation resis	tance	Polarity	d earth ance, <i>Zs</i>	RCD operating time		lest ttons		
Circuit number		Type of wiring (see Codes)	Reference Method (BS 7671)	Number of point			Max. disconnection time (<i>BS 7671</i>)	BS (EN)	Type	Rating	Short-circuit capacity Operating current, / _{An}	Operati current, Maximum	Maximum permitted Zs for installed protective device*	Ring final circuits only (measured end to end)		o end)	All circuits (complete at least one column)		Live / Live	Live / Earth	Test voltage DC	Pola	Max. measured earth fault loop impedance, <i>Zs</i>	unic	RCD	AFDD
				Nur	Live (mm ²)	cpc (mm ²)	(s)			(A)	(kA)	(mA)	(Ω)	(Line) r ₁	(Neutral) r _n	(cpc) <i>r₂</i>	$(R_{_{1}}+R_{_{2}})$	R ₂	(MΩ)	(MΩ)	(V)	(⁄)	(Ω)	(ms)	(⁄)	(⁄)
1	Outside light	A	С	1	1	1	0.4	60898	В	6	6	N/A	7.28	N/A	N/A	N/A	0.37	N/A	>500	>500	500	V	0.59	N/A	N/A	N/A
2	Spare							60898	В	6																
3	Upstairs lights	А	В	6	1	1	0.4	61009	В	6	6	30	7.28	N/A	N/A	N/A	3.05	N/A	>500	>500	500	~	3.27	20.3	~	N/A
3a	Downstairs lights	А	В	7	1	1	0.4	61009	В	6	6	30	7.28	N/A		N/A	1.09	N/A	>500	>500	500	V	1.31	20.3	~	N/A
4	Alarm	A	С	1	1	1	0.4	60898	В	6	6	N/A	7.28	N/A	N/A	N/A	0.07	N/A	>500	>500	500	V	0.39	N/A	N/A	N/A
5	Door bell	А	С	1	1	1	0.4	60898	В	6	6	N/A	7.28	N/A	N/A	N/A	0.08	N/A	>500	>500	500	V	0.30	N/A	N/A	N/A
6	Spare							60898	В	6																
7	Ground floor Shower	А	в	1	10	4	0.4	60898	В	32	6	30	1.37	N/A	N/A	N/A	0.21	N/A	>500	>500	500	V	0.43	15.3	~	N/A
8	Ground/1st/2nd floor sockets	А	В	22	2.5	1.5	0.4	60898	В	32	6	30	1.37	0.67	0.65	1.13	0.45	N/A	>500	>500	500	V	0.67	15.3	~	N/A
9	Rear entrance socket	А	В	1	2.5	1.5	0.4	60898	В	20	6	30	2.19	N/A	N/A	N/A	0.32	N/A	>500	>500	500	V	0.54	15.3	~	N/A
10	Cooker/Hob	А	В	2	6	2.5	0.4	60898	В	32	6	30	1.37	N/A	N/A	N/A	0.15	N/A	>500	>500	500	V	0.37	15.3	~	N/A
11	1st floor Shower	А	В	1	10	4	5	61009	В	50	6	30	0.87	N/A	N/A	N/A	0.21	N/A	>500	>500	500	V	0.43	15.3	V	N/A
12	Bedroom socket	А	С	1	2.5	1.5	0.4	60898	В	16	6	30	2.73	N/A	N/A	N/A	0.09	N/A	>500	>500	500	V	0.31	15.3	V	N/A
																					1	\square				
																					1	\square				
																				1						
																					1	1				<u> </u>
																				<u> </u>		-				
Ι.	STRIBUTION BOARD (DB) DETA be completed in every case)				n: DB C Dowr		front be	edroom	TESTI	ED BY	Na Siç	ime (capi inature:	tals): PE	TER WI	LSON						n: Duty h 07/07/20		r	·····		······
то	BE COMPLETED ONLY IF THE			CONI	NECTE		FCTIV		ORICI				ΔΤΙΟΝ				TEST I	NSTRI	JMENT	S (enter	serial nu	mber	agains	t each in	strumen	t used)
	pply to DB is from: (N/A														s: (N/A)	Multi-fu	nction:			(nuity:			
	ercurrent protection device for the dis sociated RCD (if any) Type: (BS EN					S EN <mark>N//</mark> Io. of po			Rating I_{Δ}	g: (<mark>N/A</mark> (N/A			Oner	ating tim	_{е (} N/А) me	Insulati (N/A				E		fault lo	oop impe)
	racteristics at this DB Confirmation of																Earth el (N/A	ectrode	resistan	ce:		RCD: (N/A			<u>-</u>)
	his report is based on the model forms shown in Appendix 6 of <i>BS 7671</i> *Where figure is not taken from <i>BS 7671</i> , state source: (

This continuation sheet is not valid if the serial number has been defaced or altered

23649180

GENERAL CONTINUATION SHEET

M18C

NOTES

1st/2nd floor Section 701 Installation containing a bath or shower V

NOTES FOR RECIPIENT

THIS CONDITION REPORT IS AN IMPORTANT AND VALUABLE DOCUMENT WHICH SHOULD BE RETAINED FOR FUTURE USE

The purpose of periodic inspection is to determine, so far as is reasonably practicable, whether an electrical installation is in a satisfactory condition for continued service. This report provides an assessment of the condition of the electrical installation identified overleaf at the time it was inspected and tested, taking into account the stated extent of the installation and the limitations of the inspection and testing.

This report has been issued in accordance with the national standard for the safety of electrical installations, *BS* 7671: 2018 – *Requirements for Electrical Installations*.

The report identifies any damage, deterioration, defects and/or conditions found by the inspector which may give rise to danger (see PART 6), together with any items for which improvement is recommended.

If you were the person ordering this report, but not the user of the installation, you should pass this report, or a full copy of it including these notes, the schedules and additional pages (if any), immediately to the user.

This report should be retained in a safe place and shown to any person inspecting or undertaking further work on the electrical installation in the future. If you later vacate the property, this report will provide the new user with an assessment of the condition of the electrical installation at the time the periodic inspection was carried out.

Where the installation incorporates a residual current device (RCD) there should be a notice at or near the device stating that it should be tested every six months. For safety reasons it is important that this instruction is followed.

For safety reasons, the electrical installation should be re-inspected at appropriate intervals by a skilled person or persons, competent in such work.

The recommended date by which the next inspection should be carried out is stated in PART 5 of this report. There should also be a notice at or near the main switchboard or distribution board/consumer unit indicating when the next inspection of the installation is due.

You should have received the report marked 'Original' and the contractor should have retained the report marked 'Duplicate'.

This report form is intended to be issued only for the purpose of reporting on the condition of an existing electrical installation and must not be issued to certify new electrical installation work including the replacement of a distribution board or consumer unit.

The report consists of at least six numbered pages. Additional numbered pages may have been provided to permit further relevant information relating to the installation to be recorded. For installations having more than one distribution board or more circuits than can be recorded on PART 12, one or more additional *Schedules of Circuit Details and Test Results* should form part of the report. The report is invalid if any of the schedules identified in PART 10 are missing.

PART 7 (Details and limitations) should identify fully the extent of the installation covered by this report and any limitations on the inspection and testing. The inspector should have agreed these aspects with the person ordering the report and with other interested parties (licensing authority, insurance company, mortgage provider and the like) before the inspection was carried out.

Operational limitations may have been encountered during the inspection such as inability to gain access to parts of the installation or to an item of equipment. The inspector should have noted any such limitations in PART 7. It should be noted that the greater the limitations applying to a report, the less its value from the safety aspect.

A declaration should have been given by the inspector in PART 4 of the report. The declaration must reflect the statement given in PART 3, which summarises the observations and recommendations made in PART 6. Where one or more observations have been made in PART 6, the Classification code given to each by the inspector indicates the degree of urgency with which remedial action needs to be taken to restore the installation to a safe working condition.

Where the inspector has indicated an observation as code C1 (danger present) **the safety of those using the installation is at risk.** Wherever practicable, items classified as (C1) should be made safe on discovery, and it is recommended that a skilled person(s) competent in electrical installation work undertakes the necessary remedial work immediately.

Where the inspector has indicated an observation as code C2 (potentially dangerous) **the safety of those using the installation may be at risk**, and it is recommended that a skilled person(s) competent in electrical installation work undertakes the necessary remedial work as a matter of urgency.

Where the inspector has indicated that an item requires further investigation (FI), the investigation should be carried out without delay to determine whether danger or potential danger exists. For further guidance on the Classification codes, please see the reverse of page 2.

Where the installation can be supplied by more than one source, such as the public supply and a standby generator or microgenerator, this should be identified in PART 8 *Supply Characteristics and Earthing Arrangements*, and the *Schedules of Circuit Details and Test Results* (PART 12) compiled accordingly.

Where inadequacies in the intake equipment have been observed (Item 1 of PART 10), the person ordering the inspection should inform the distributor and/or supplier as appropriate.

Should the person ordering this report have reason to believe that it does not reasonably reflect the condition of the electrical installation reported on, that person should in the first instance raise the specific concerns in writing with the contractor.

GUIDANCE FOR RECIPIENTS ON THE CLASSIFICATION CODES Only one Classification code should be given for each recorded Observation

Classification code C1 (Danger present)

Where an observation has been given a Classification code C1, the safety of those using the installation is at risk and immediate remedial action is required.

The person responsible for the maintenance of the installation is advised to take action without delay to remedy the observed deficiency in the installation, or to take other appropriate action (such as switching off and isolating the affected part(s) of the installation) to remove the danger. The contractor issuing this report will be able to provide further advice.

NICEIC makes available 'Electrical Danger Notification' forms to enable inspectors to record, and then to communicate to the person ordering the report, any dangerous condition discovered.

Classification code C2 (Potentially dangerous)

Classification code C2 indicates that, whilst those using the installation may not be at immediate risk, urgent remedial action is required to remove potential danger. The contractor issuing this report will be able to provide further advice.

It is important to note that the recommendation given at PART 5 of this report (Next Inspection) for the maximum interval until the next inspection is conditional upon all items which have been given a Classification code C1 and code C2 being remedied immediately and as a matter of urgency, respectively.

It would not be reasonable for the inspector to indicate that the installation is in a satisfactory condition if any observation in this report has been given a code C1 or code C2 classification.

Classification code C3 (Improvement recommended)

Where an observation has been given a Classification code C3, the inspection and/or testing has revealed a non-compliance with the current safety standard which, whilst not presenting immediate or potential danger, would result in a significant safety improvement if remedied. Careful consideration should be given to the safety benefits of improving these aspects of the installation. The contractor issuing this report will be able to provide further advice.

Code FI (Further investigation required without delay)

It should usually be possible for the inspector to attribute a Classification code to each observation without indicating a need for further investigation.

However, where 'FI' has been entered against an observation the inspector considers that further investigation of that observation is likely to reveal danger or potential danger that, due to the agreed extent or limitations of the inspection and/or testing, could not be fully identified at the time.

It would not be appropriate for the inspector to indicate that the installation is in a satisfactory condition if there is reasonable doubt as to whether danger or potential danger exists. Consequently, where the inspector has indicated 'Further investigation required without delay' (FI) the overall assessment of the installation (PART 3) should be marked as 'Unsatisfactory'.

If the inspector has indicated that an observation requires further investigation without delay, the person ordering this report is advised to arrange for the contractor issuing the report (or another skilled person or persons competent in such work) to undertake further examination of that aspect of the installation as a matter of urgency, to determine whether or not danger or potential danger exists.

Further information

Further information on the application of Classification codes, primarily aimed at inspectors but of possible interest to persons ordering condition reports, can be found in Electrical Safety First's Best Practice Guide No 4 *Electrical installation condition reporting: Classification Codes for domestic and similar electrical installations.* The guide can be viewed or downloaded free of charge from www. electricalsafetyfirst.org.uk