



Domestic/Landlord Gas Safety Record

(Integrity, Construction and Lining) has been carried out.

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues

Certificate Reference

24 Johnson Avenue

Certificate No: 1

Engineers Details						Insta	Installation Details					Client Details							
Trading Title		GW Plumbing and Heating					Installation Address						Client Address	: I	Houses				
Address		7 Hertford Close				\neg	11000	24 Johnson Avenue					71001000	90					
		Syston						Lenton						Paget	Street				
		Leicester						Nottingham						Loughborough					
		Post Code: LE7 2FA						Post Code: NG7 2BX						Post Code: LE11 5DT				SDT	
Gas Safe No:		944162 Telephone No: 07788379040				Tel	Telephone No:						 Telephon						
Appliance Details						Inspection Details													
	Locatio		Appliance Type	Make	Model	Combustion LOW (CO2% or CO/CO2 ratio)	Combustion HIGH (CO2% or CO/CO2 ratio)	Heat Input (KW) or Operating Pressure	CO Reading (ppm)	Appliance Inspected (YES/NO/NAVIO) (VD. = Vesual Imperdor Only)	FlueType (OF/RS/FL)	Landlords Appliance (YES/NO/NA)	Safety Device(s) Correct Operation (YES/NO/NA)	Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)	
1	Bathro	om	Combi boiler	Main	Eco Compact 30 Combi	0.0001	0.0009	29.9 kw	90PPM	YES	RS	YES	YES	NA	YES	PASS	NO	YES	
2	Kitche	n Hob		Lamona	4 Burner	NA	NA	10.5 kw	NA	YES	FL	YES	YES	YES	NA	NA	NO	YES	
3																			
4																			
5																			
Faults/Notes							Remedial Work Taken									Warning Notice Fixed			
1																			
2																			
3																			
4																			
5																			
	ergency Cont essible:	trol Valve	YES		Signatures Report Issued By: Gas ID Number:									555551	5555519				
Gas	Installation I	Pipework	Visual Inspection Sa		Name: Grant Wright Signed: Date:								Mon-22-07-2024						
Nun	nber of Appli	ances Te	sted: 2	Equipotential	Bonding: YES	1	Report Received By:												
	NEXT INSPECTION DUE ON OR BEFORE: Mon-28-07-2025 Installation Pass: YES							e: Signed:						Date:	Mon-22-07-2024				
	CO Alarm fitted & working? YES Smoke alarm fitted & working? This Gas Safety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk For appliances not owned by the Landlord the recorded 'Appliance Safe' response is based on a visual check for obvious de												.uk ous defects c	only.					