

Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out.

Certificate Reference

31 Bute Avenue

Certificate No: 1

Engineers Details							Inst	Installation Details					Client Details								
Trading Title		GW Plumbing and Heating						tallation						Client		Houses					
Address		7 Hertford Close						dress	31 Bute Avenue					Address	ss 90						
		Syston							Lenton						Paget Street						
		Leicester							Nottingham						Loughborough						
		Post Code: LE7 2FA							Post Code: NG7 1QB				7 1QB				Post Coo	de: LE115	5DT		
Gas Safe No:		944162 Telephone No: 07788379040					Te	Telephone No:						Telephone No:							
A	ppliance De	tails]	Inspection Details]					
	Locatic	Location		се Туре	Make	Model	Combustion LOW (C02% or CO/C02 ratio)	Combustion HIGH (CO2% or CO/CO2 ratio)	Heat Input (KW) or Operating Pressure	CO Reading (ppm)	Appliance Inspected (YES/NO/NA/VIO) (V/D = Vuua Importon Only)	FlueType (OF/RS/FL)	Landlords Appliance (YES/NO/NA)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)		
1	Bathro	om	Combi boiler		Main	Eco Combi 30	0.0001	0.0003	29.8 kw	30PPM	YES	RS	YES	YES	NA	YES	PASS	NO	YES		
2																					
3																					
4																					
5																					
Faults/Notes							Remedial Work Taken									Warning Notice Fixed					
1	1																				
2																					
3	1																				
4																					
5																					
Emergency Control Valve YES Gas Tightness Satisfactory: YES									Signatures Gas ID Number:										5555519		
Accessible: YES Gas Ingritiess Satisfactory: YES Gas Installation Pipework Visual Inspection Satisfactory: YES								Report Issued By:									000001	5555519			
Gas	s Installation I	Pipework	< Visual Ins	pection Sa	atistactory:] Na	Name: Grant Wright Signed: Date							Mon-22-07-2024							
Nur	mber of Appli	ances Te	ested:	1	Equipotential E	Bonding: YES] Re	Report Received By:													
	XT INSPECTI BEFORE:	ION DUE ON SL		Sun-27-07	Gun-27-07-2025 Installation Pass:] Na	ame: 🗌			Signed:					Date:	Mon-22	2-07-2024			
CO Alarm fitted & working? YES Smoke alarm fitted & working? YES]	F.	This Gas Safety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk												

For appliances not owned by the Landlord the recorded 'Appliance Safe' response is based on a visual check for obvious defects only.