

## Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out. This safety check complies with (but is not limited to) Regulation 26(9) of GSIUR.

Certificate Reference

parrs2

Certificate No: 002

Engineers Details								Installation Details						Client Details							
Trading Title		Scott Mee						llation						Client Addre		ouses					
Address		9 Kirkstone Ave					Addr	ess	26 Chest	hestnut Street					90 Pa	90 Paget St Loughborough					
		Heanor Derbyshire							Loughborough					Lough							
		Post Code: De757uj								Post Code: LE113BE						Post Code: LE115DT					
Gas Safe No:		670139 Telephone No: 07576807489						ephone No:					- Teleph	38	$\neg$						
Appliance Details								Inspection Details													
		etano	Γ										T		T			<u> </u>	<u> </u>		
	Locatio	Location		nce Type	Make	Model	CO2 Reading (%)	CO Reading (ppm)	FlueType (OF/RS/FL)	Appliance Inspected (YES/NO/NA/VIO) WD = Vuud Inspecton Only	Combustion Analysis Reading (CO/CO2)	Landlords Appliance (YES/NO/NA)	Operating Pressure(mbar) or Heat Input(KW)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)		
1	Kitche	Kitchen		bi Boiler	Baxi	Baxi	8.8	160	RS	YES	0.0014	YES	21.31 mbar	YES	NA	YES	PASS	NA	YES		
2																					
																		<u> </u>			
3																		<u> </u>			
4																		<u> </u>			
5																					
Faults/Notes									Remedial Work Taken									Warning Notice Fixed			
1																					
2																					
3																					
4																					
5																					
Emergency Control Valve									S												
Accessible:									t Issued By:								575637	5756370			
Gas	Installation	Pipework	< Visual Ir	spection S	atisfactory:	ne: s	Scott Mee Signed:				d:	SMee Date:			: Thu-07-	Thu-07-Nov-2024					
Nun	nber of Appli	iances Te	ested:	1	Equipotential I	Bonding: Yes	] Rep	ort Re	t Received By:						_						
NEXT INSPECTION DUE ON Sat-18-Oct-2025 Installation Pass: Yes						Nan					Signed:			Shu Date:		Thu-07-	Thu-07-Nov-2024				
CO Alarm fitted & working? YES Smoke alarm fitted & working? YES							]	-	This Gas Safety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk												

This Gas Safety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk For appliances not owned by the Landlord the recorded 'Appliance Safe' response is based on a visual check for obvious defects only.